




Under 23 United States Code §148 and 23 United States Code §409, safety data, reports, surveys, schedules, lists compiled or collected for the purpose of identifying, evaluating, or planning the safety enhancement of potential crash sites, hazardous roadway conditions, or railway-highway crossings are not subject to discovery or admitted into evidence in a Federal or State court proceeding or considered for other purposes in any action for damages arising from any occurrence at a location mentioned or addressed in such reports, surveys, schedules, lists, or data.

Date: 7/15/2019 Author: tinscha Path: \\parametrix.com\pmx\PSO\Projects\Clients\1896-CityOfBrenton\554-1896-156 SR 303 Corridor Study\99\Svcs\GIS\MapDocs\SR303_CrashSummary.mxd





Source: WSDOT, © Mapbox, © OpenStreetMap




- Crash Location on Corridor (1205)
- Crash Involving Bus (13)
- Crash Involving Pedestrian (24)
- Crash Involving Bicycle (14)
- Serious Injury Crash (13)
- Fatal Crash (2)
- Intersection (Collisions/MEV)

Under 23 United States Code §148 and 23 United States Code §409, safety data, reports, surveys, schedules, lists compiled or collected for the purpose of identifying, evaluating, or planning the safety enhancement of potential crash sites, hazardous roadway conditions, or railway-highway crossings are not subject to discovery or admitted into evidence in a Federal or State court proceeding or considered for other purposes in any action for damages arising from any occurrence at a location mentioned or addressed in such reports, surveys, schedules, lists, or data.

Date: 7/15/2019 Author: tinscha Path: \\parametrix.com\pmx\PSOI\Projects\Clients\1896-CityOfBremerton\554-1896-156 SR 303 Corridor Study\99Srcs\GIS\MapDocs\SR303_CrashSummary.mxd




Source: WSDOT, © Mapbox, © OpenStreetMap




- Crash Location on Corridor (1205)
- Crash Involving Bus (13)
- Crash Involving Pedestrian (24)
- Crash Involving Bicycle (14)
- Serious Injury Crash (13)
- Fatal Crash (2)
- Intersection (Collisions/MEV)

Under 23 United States Code §148 and 23 United States Code §409, safety data, reports, surveys, schedules, lists compiled or collected for the purpose of identifying, evaluating, or planning the safety enhancement of potential crash sites, hazardous roadway conditions, or railway-highway crossings are not subject to discovery or admitted into evidence in a Federal or State court proceeding or considered for other purposes in any action for damages arising from any occurrence at a location mentioned or addressed in such reports, surveys, schedules, lists, or data.

Date: 7/15/2019 Author: tinscha Path: \\parametrix.com\pmx\PSO\Projects\Clients\1896-CityOfBrenton\554-1896-156 SR 303 Corridor Study\99SVcs\GIS\MapDocs\SR303_CrashSummary.mxd



Source: WSDOT, © Mapbox, © OpenStreetMap



- Crash Location on Corridor (1205)
- Crash Involving Bus (13)
- Crash Involving Pedestrian (24)
- Crash Involving Bicycle (14)
- Serious Injury Crash (13)
- Fatal Crash (2)
- Intersection (Collisions/MEV)